

TO: Distribution
FROM: M. S. Hodges
DATE: September 5, 1974
SUBJECT: Multics Change Requests

Enclosed are copies of Multics Change Requests which were approved from August 16 to August 31, 1974.

Multics Project internal working documentation. Not to be reproduced or distributed outside the Multics Project.

MULTICS CHANGE REQUEST

MCR 635
Page 1 of 1 Pages

TITLE: Modifications to NCP to standardize access control and handle process termination conditions.
AUTHOR: D. Wells

STATUS	DATE
Written	74.06.
Approved <i>H</i>	8/27/74
Rejected	
Postponed <i>H</i>	7/2/75
Withdrawn	
Expires	2/27/75

SOURCE: (if external) e.g., "User", "Marketing"

CLASSIFICATION	JUSTIFICATION	
Incompatible Change	Marketing Requirement	Replaced by proposal MCR _____
Extension	X Conformance to Standard	Implemented in System _____
Restriction	Increased Consistency	Objections/Comments: Needs further design review.
Performance Improvement	Simplification	
X Reliability Improvement	Generalization	
	Bug Fix	

Use these headings: REASONS, SUMMARY, IMPLICATIONS, DETAILED PROPOSAL (Optional)

REASONS: The Network Control Program does not currently properly close out connections when a process terminates.
The Network Control Program is not properly turned off when the Network Daemon process terminates.
Access to the "connect" function is determined in a non-standard manner -- i.e., a segment in the hierarchy is checked to see if the user had access to that segment. This requires that the Ring 0 NCP know about at least one pathname in the onli e hierarchy.

SUMMARY:
The Network Control Program will be modified to use the I/O Assignment Manager to properly close and deactivate any connections that a user had when his process terminated.
The Network Control Program will be modified to use the I/O Assignment Manager to shut down the Network when the Network Daemon process terminates.
Access to the "connect" function will be determined by a gate to be added. Access to this gate will be dynamically modified via a privileged call to the NCP. The Network Daemon process overseer will be modified to initialize this access when it initializes the Network Control Program.

IMPLICATIONS:
The number of IOAT entries will have to be increased to support this function. These entries are wired down (though the NCP use of them does not intrinsically require that they be wired down) -- thus decreasing the size of the paging pool. Because the size of the IOAT is to be determined by a configuration card, this can be managed by system maintenance personnel.

MULTICS CHANGE REQUEST		MCR <u>710</u> Page <u>1</u> of <u>1</u>
TITLE: <u>Fix Bugs Reading HALF/FULL switch in BOS and Multics</u>		STATUS
AUTHOR: <u>Noel I. Morris and Bernard S. Greenberg</u>		Written <u>8/12/74</u>
SOURCE: (if external) e.g., "User", "Marketing" <u>Internal</u>		Approved <u>8-20-74</u>
		Rejected
		Postponed
		Withdrawn
		Expires <u>2-20-75</u>

CLASSIFICATION	JUSTIFICATION	
<input type="checkbox"/> Incompatible Change	<input type="checkbox"/> Marketing Requirement	Replaced by proposal MCR _____
<input type="checkbox"/> Extension	<input type="checkbox"/> Performance to Standard	Implemented in System _____
<input type="checkbox"/> Restriction	<input type="checkbox"/> Increased Consistency	Objections/Comments:
<input type="checkbox"/> Performance Improvement	<input type="checkbox"/> Simplification	
<input type="checkbox"/> Reliability Improvement	<input type="checkbox"/> Generalization	
<input type="checkbox"/>	<input checked="" type="checkbox"/> Unreported Bug Fix	
<input type="checkbox"/>	<input type="checkbox"/>	

Use these headings: REASONS, SUMMARY, IMPLICATIONS, DETAILED PROPOSAL (Optional)

REASONS:

Improper documentation has led to the use of the wrong RSW instruction in determining the setting of HALF/FULL switches for memory on the CPU configuration panel. This bug exists both in the BOE subroutine, getportinfo, and in the Multics initialization primitive, scas_init.

Summary:

Correct the code to use the proper RSW instruction.

MULTICS CHANGE REQUEST	MCR <u>711</u> Page <u>1</u> of <u>1</u>
TITLE: Make a branch for configuration deck in system_library_1	STATUS
AUTHOR: <u>Noel I. Morris</u>	Written <u>8/12/74</u> Approved <u>8/20/74</u> Rejected
SOURCE: (if external) e.g., "User", "Marketing" In ternal	Postponed Withdrawn Expires <u>2/20/75</u>

CLASSIFICATION	JUSTIFICATION	REASON
<input type="checkbox"/> Incompatible Change	Marketing Requirement	Replaced by proposal MCF _____ Implemented in System _____
<input checked="" type="checkbox"/> Extension	Conformance to Standard	Objections/Comments: Correct ACL should be placed in header so users don't have access to this.
<input type="checkbox"/> Restriction	<input checked="" type="checkbox"/> Increased Consistency	
<input type="checkbox"/> Performance Improvement	<input checked="" type="checkbox"/> Simplification	
<input type="checkbox"/> Reliability Improvement	<input checked="" type="checkbox"/> Generalization	
<input type="checkbox"/>	Bug Fix	

Use these headings: REASONS, SUMMARY, IMPLICATIONS, DETAILED PROPOSAL (Optional)

REASONS:
 Many outer ring programs need access to the Multics configuration deck (e.g. on-line TandD). If a branch is created for the config deck in system_library_1, then the segment "config_deck" can be initiated and read without having to call into ring 0 to copy it out. This mechanism has already been used for the SLT segment and its name table.

Summary:
 Change the SLT template include files to cause a branch to be created for "config_deck".

MULTICS CHANGE REQUEST		MCR <u>712</u> Page <u>1</u> of <u>1</u>
TITLE: Make a segment for the BOS toehold		STATUS
		Written <u>8/12/74</u>
AUTHOR: <u>Noel I. Morris</u>		Approved <u>8/20/74</u>
		Rejected
SOURCE: (if external) e.g., "User", "Marketing" Internal		Postponed
		Withdrawn
		Expires <u>2/20/75</u>

CLASSIFICATION	JUSTIFICATION	REASON
<input checked="" type="checkbox"/> Incompatible Change	Marketing Requirement	Replaced by proposal MCF _____
<input checked="" type="checkbox"/> Extension	Conformance to Standard	Implemented in System _____
<input type="checkbox"/> Restriction	<input checked="" type="checkbox"/> Increased Consistency	Objections/Comments: .
<input checked="" type="checkbox"/> Performance Improvement	<input checked="" type="checkbox"/> Simplification	
<input checked="" type="checkbox"/> Reliability Improvement	<input checked="" type="checkbox"/> Generalization	
	Bug Fix	

Use these headings: REASONS, SUMMARY, IMPLICATIONS, DETAILED PROPOSAL (Optional)

REASONS:

Multics initialization primitives currently "know" that the 1024 word block of core which contains the BOS toehold should not be assigned for paging. Programs which return to BOS also "know" the absolute location of the toehold. These wired in values can be removed from all but one program if a 1 page segment containing the BOS toehold is constructed during system initialization by bootstrap1.

Summary:

Modify bootstrap1 to construct the segment "bos_toehold" when it sets up the initial descriptor segment. Change the SLT template include files to include this new segment.

Implications:

Unless segments are shuffled slightly, the segment numbers of emergency_shutdown and the sst_seg will change.

MULTIPLE CHANGE PERMIT		MCP <u>713</u> Page <u>1</u> of <u>1</u>
TITLE: <u>vfile_bugs</u>	AUTHOR: <u>M.D. MacLaren</u>	STATUS: <u>1</u> Written <u>8/8/74</u> Approved <u>8/20/74</u> Rejected
SOURCE: (if external) e.g., "User", "Marketing"		Postponed Withdrawn Expires <u>2/20/75</u>

CLASSIFICATION	JUSTIFICATION	
<input type="checkbox"/> Incompatible Change	<input type="checkbox"/> Marketing Requirement	Replaced by proposal MCP _____
<input type="checkbox"/> Extension	<input type="checkbox"/> Performance to Standard	Implemented in System _____
<input type="checkbox"/> Restriction	<input type="checkbox"/> Increased Consistency	Objections/Comments:
<input type="checkbox"/> Performance Improvement	<input type="checkbox"/> Simplification	
<input type="checkbox"/> Reliability Improvement	<input type="checkbox"/> Generalization	
<input type="checkbox"/>	<input type="checkbox"/> unreported	
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/> Bug Fix	

Use these headings: REASONS, SUMMARY, IMPLICATIONS, DETAILED PROPOSAL (Optional)

REASONS: Recent installation of vfile_ has compiler-caused *bug that prevents use of sequential files. Testing uncovered an unrelated bug in the program that results in an error when attempt is made to backspace beyond beginning of a segment.

SUMMARY: Replace open_seg_file in bound_vfile_ with a corrected version compiled using the experimental compiler (in which compiler bug is fixed).

IMPLICATIONS: Sequential files will have correct format (instead of slightly incorrect format). Old files will work as well as they do now.

NOTE: It is not feasible to change the program to get around the compiler bug. The only alternatives to using the ex1 compiler are to reinstall the old open_seg_file (complete with bug) or compile using the old non_EIS compiler).

* Compiler bug #1203



MULTICS CHANGE REQUEST

MCR 714

TITLE: Make changes to Answering Service to Implement Access Isolation Mechanism

STATUS DATE

AUTHOR: Paul A. Green

Written 08/12/74

Approved 8/20/74

Rejected

SOURCE: (if external; e.g., "User", "Marketing")

Postponed

Withdrawn

Expires 2/20/75

CLASSIFICATION JUSTIFICATION

Replaced by proposal MCR

Incompatible Marketing

Change Requirement Implemented in System

Extension Conformance

Performance to Standard Objections/Comments:

Restriction Increased

Improvement Consistency

Reliability

Improvement Simplification

Reliability

Improvement Generalization

Bug Fix

Use these headings: REASONS, SUMMARY, IMPLICATIONS, and optionally DETAILED PROPOSAL

REASONS

See MTB-078.

SUMMARY

Modify answering service include files and programs, and administrative tools, as outlined in MTB-078 (as modified by MTB-100 terminology) to provide AIM attributes for persons, projects, terminals, etc.

IMPLICATIONS

Covered by MTB-078 and a previous design review. Adds new features and complexity to the answering service.

Memo to: Multics Change Review Board
From: Paul Green
Re: Summary of Changes to Answering Service for AIM

The proposed changes will:

- . record an authorization attribute (bit (72) aligned) for each entry in the PNT (per person), SAT (per project), PDT (per user), and CCT (per terminal; new table, called the Channel Control Table).
- . provide tools to update and maintain these fields, under the control of the System Security Administrator.
- . compute the access authorization of a process based on the attributes of the person, project, user, terminal, and login options.
- . print the computed authorization of the process at login time (if it is greater than unclassified).
- . provide options to the login and new_proc commands to specify the requested authorization, provide a login option to set the default authorization.
- . provide the ability (on a per-person basis, in the PNT) to have the system assign passwords when the -change_password login option is given.
- . be documented in the style of the MPM/SPS/or PLM, as appropriate.

The individual programs and include files which will be changed are rather numerous, and so are not specified in the MCR or this note.

The above ~~requirements~~ requirements are from Honeywell's proposal to the Air Force; as time goes by we may add more changes to the above list.

MULTI-CHANGE REQUEST

MCR 715
Page 1 of 1

TITLE: Add name tdc_m to hcs

STATUS	DATE
Written	8-12-74
Approved	8/20/74
Rejected	

AUTHOR: Bill Silver

SOURCE: (if external) e.g., "User", "Marketing"

Postponed	
Withdrawn	
Expires	2/30/75

CLASSIFICATION	JUSTIFICATION	
<input type="checkbox"/> Incompatible Change	<input type="checkbox"/> Marketing Requirement	Replaced by proposal MCP _____
<input checked="" type="checkbox"/> Extension	<input type="checkbox"/> Conformance to Standard	Implemented in System _____
<input type="checkbox"/> Restriction	<input type="checkbox"/> Increased Consistency	Objections/Comments:
<input type="checkbox"/> Performance Improvement	<input type="checkbox"/> Simplification	
<input type="checkbox"/> Reliability Improvement	<input checked="" type="checkbox"/> Generalization	
<input type="checkbox"/>	<input type="checkbox"/> Bug Fix	
<input type="checkbox"/>	<input type="checkbox"/>	

Use these headings: REASONS, SUMMARY, IMPLICATIONS, DETAILED PROPOSAL (Optional)

REASONS: Adding the name tdc_m to the gate hcs is a first step in the plan to remove all hcs entries which reference tdc_m. This is being done for reasons of security and to allow tdc_m to be removed from ring zero once ioi is installed.

SUMMARY: The name tdc_m will be added to the gate hcs. All calls in the tape I/O modules tape and nstd which are of the form hcs\$tdc_mxxxx must be changed to calls of the form tdc_m\$tdc_mxxxx.

IMPLICATIONS: When all system maintained and user programs have been changed to call tdc_m rather than hcs, the entry points in hcs which reference tdc_m can be deleted. At this time a higher ring tdc_m or a new gate tdc_m will have to be installed.

MULTIPLE CHANGE REQUEST		MCP <u>716</u> Form <u>1</u> of <u>1</u>
TITLE: Deletion of set file protect on tape detach		STATUS: <u>8-12-74</u>
AUTHOR: <u>Bill Silver</u>		Approved: <u>8/20/74</u>
SOURCE: (if external) e.g., "User", "Marketing"		Rejected: _____
		Postponed: _____
		Withdrawn: _____
		Expires: <u>2/20/75</u>

CLASSIFICATION	JUSTIFICATION	
Incompatible Change	Marketing Requirement	Replaced by proposal MCP _____
Extension	Conformance to Standard	Implemented in System _____
Restriction	Increased Consistency	Objections/Comments:
Performance Improvement	Simplification	
Reliability Improvement	Generalization	
<input checked="" type="checkbox"/> Improvement	unreported	
	<input checked="" type="checkbox"/> Bug Fix	

Use these headings: REASONS, SUMMARY, IMPLICATIONS, DETAILED PROPOSAL (Optional)

REASONS: tdcn currently issues a set file protect command whenever it rewinds and unloads a tape. This forces the operators to remove the tape reel from the handler in order to turn on write permit. This is an unnecessary inconvenience. Handler malfunctions sometimes compound the problem.

SUMMARY: Stop tdcn from issuing the set file protect command.

IMPLICATIONS: This operational problem will be solved.

DETAILED PROPOSAL: The set file protect command set up in tape_data will be changed to a reset status command.

MULTI-CHANGE REQUEST		MCR <u>717</u> Page <u>1</u> of <u>1</u>
TITLE: <u>Fix BOS to run with Reader on any channel</u>		STATUS
AUTHOR: <u>N. I. Morris</u>		Written <u>8/9/74</u>
SOURCE: (if external) e.g., "User", "Marketing" <u>Internal</u>		Approved <u>8/20/74</u>
		Rejected
		Postponed
		Withdrawn
		Expires <u>2/20/75</u>

CLASSIFICATION	JUSTIFICATION	Replaced by proposal MCR _____
<input type="checkbox"/> Incompatible Change	<input type="checkbox"/> Marketing Requirement	Implemented in System _____
<input checked="" type="checkbox"/> Extension	<input type="checkbox"/> Performance to Standard	Objections/Comments:
<input type="checkbox"/> Restriction	<input checked="" type="checkbox"/> Increased Consistency	
<input type="checkbox"/> Performance Improvement	<input checked="" type="checkbox"/> Simplification	
<input type="checkbox"/> Reliability Improvement	<input checked="" type="checkbox"/> Generalization	
	<input type="checkbox"/> Bug Fix	

Use these headings: REASONS, SUMMARY, IMPLICATIONS, DETAILED PROPOSAL (Optional)

REASONS:

BOS currently can only run with a card reader configured to IOM channel 16g. With the increased use of URMPC's, this becomes a serious restriction.

Summary:

The card reader channel number is deposited in memory when a card is read via the IOM bootload mechanism. A simple change to the BOSLDR 5-card loader can enable this channel number to be preserved. The BOS loader program, LOADDMM, can then pick up this channel number and save it in BOS common. This saved channel number can be used by BOS whenever cards are to be read.

Change the CARDS command to accept an optional argument which is a card reader channel number. This will enable changing the card reader channel during BOS operation.

MULTICS CHANGE REQUEST

MCR 718

TITLE: Prepare library programs for unbundled library

STATUS DATE

AUTHOR: Arlene J. Scherer

Written 08/08/74

Approved 8/20/74

Rejected

SOURCE: (if external; e.g., "User", "Marketing")

Postponed

Withdrawn

Expires 2/20/75

CLASSIFICATION JUSTIFICATION

Replaced by proposal MCR

Incompatible Marketing

Implemented in System

Change Requirement

Conformance

Extension to Standard

Objections/Comments:

Increased

Restriction Consistency

Performance

Improvement Simplification

Reliability

Improvement Generalization

Bug Fix

Use these headings: REASONS, SUMMARY, IMPLICATIONS, and optionally, DETAILED PROPOSAL

REASON:

PART ONE: Add the unbundled library to all programs which look at the system libraries. Programs involved are:
 get_library_segment and related control files
 submission_test
 update_seg (subroutine upd_doc_task_)
 the uninstalled Multics library descriptor (library_print).

PART TWO: Part Two modifies the request expressed in Part Four of MCR 684 to add a "-sys" option to submission test calls for the purpose of allowing a Subsystem or other non standard library to be used for comparison of source and bindfiles. Upon further thought, a "-control_dir" ("-cd") argument will better serve this need by allowing the user to specify a control_dir in which his own version of the gis control segments may be found, enabling him to use any arbitrary set of paths.

SUMMARY:

These changes need to be implemented ahead of any actual unbundled library installations. In addition, users and staff should be notified (perhaps via an MTB) of the intended establishment of the unbundled library, and what its planned contents are.

MULTIPLY CHANGE REQUEST		MCP <u>719</u> Part <u>1 of 1</u>
TITLE: <u>Install compare_object</u>		STATUS
AUTHOR: <u>Richard Barnes</u>		Written <u>8-14-74</u>
SOURCE: (if external) e.g., "User", "Marketing"		Approved <u>8/20/74</u>
		Rejected
		Postponed
		Withdrawn
		Expires <u>2/20/75</u>

CLASSIFICATION	JUSTIFICATION	
<input type="checkbox"/> Incompatible Change	<input type="checkbox"/> Marketing Requirement	Replaced by proposal MCP _____
<input type="checkbox"/> Extension	<input type="checkbox"/> Conformance to Standard	Implemented in System _____
<input type="checkbox"/> Restriction	<input checked="" type="checkbox"/> Increased Consistency	Objections/Comments: Install in Tools
<input type="checkbox"/> Performance Improvement	<input type="checkbox"/> Simplification	
<input type="checkbox"/> Reliability	<input type="checkbox"/> Generalization	
<input checked="" type="checkbox"/> Improvement	<input type="checkbox"/> Bug Fix	
<input type="checkbox"/>	<input type="checkbox"/>	

Use these headings: REASONS, SUMMARY, IMPLICATIONS, DETAILED PROPOSAL (Optional)

REASONS: `compare_object` enables a user to determine if two object segments, possibly compiled by different versions of a compiler, are essentially identical. This enables installation personnel to ensure that a submitted source segment produced a submitted object segment with a current compiler.

SUMMARY: `compare_object (cob)` compares the text, link, and definition sections of two object segments. The user can also specify that certain sections should not be compared. Another entry point, `compare_object_`, is provided so that this comparison can be achieved from a program. `compare_object_` is a function returning bit (1) aligned.

MULTIPLE CHANGE PROJECT		MCP <u>720</u> Page <u>1</u> of <u>1</u>
TITLE: Implement new matching strategy in acl_commands		STATUS: <u>8-14</u>
AUTHOR: Steve Herbst		Approved <u>8/20/74</u>
SOURCE: (if external) e.g., "User", "Marketing"		Rejected
		Postponed
		Withdrawn
		Expires <u>2/20/75</u>

CLASSIFICATION	JUSTIFICATION	
<input checked="" type="checkbox"/> Incompatible Change	Marketing Requirement	Replaced by proposal MCP _____
<input type="checkbox"/> Extension	Conformance to Standard	Implemented in System _____
<input type="checkbox"/> Restriction	Increased Consistency	Objections/Comments: Make sure that this is properly documented.
<input type="checkbox"/> Performance Improvement	Simplification	
<input type="checkbox"/> Reliability Improvement	<input checked="" type="checkbox"/> Generalization	
<input type="checkbox"/>	Bug Fix	
<input type="checkbox"/>		

Use these headings: REASONS, SUMMARY, IMPLICATIONS, DETAILED PROPOSAL (Optional)

REASONS: A redefinition of the matching strategy for missing components in acl names was proposed in MTB-092. The new extended_access_commands uses this new matching strategy. The regular acl commands should use it too.

SUMMARY: Change acl_commands to call find_common_acl_names_.

IMPLICATIONS: Change in user interface. Users must be warned in advance.

MULTIPLE CHANGE REQUEST

MCP 721
Page 1 of 1

TITLE: Bind together debug, trace_stack, and trace

STATUS	
Written	740815
Approved	8/20/74
Rejected	
Postponed	
Withdrawn	
Expires	2/20/75

AUTHOR: Barry L. Wolman

SOURCE: (if external) e.g., "User", "Marketing"

CLASSIFICATION	JUSTIFICATION	
	Incompatible Change	Marketing Requirement
		Implemented in System
X	Extension	Conformance to Standard
	Restriction	Increased Consistency
X	Performance Improvement	Simplification
	Reliability Improvement	Generalization
		Bug Fix

Replaced by proposal MCP _____

Objections/Comments: _____

Use these headings: REASONS, SUMMARY, IMPLICATIONS, DETAILED PROPOSAL (Optional)

REASONS: The three debugging programs debug, trace_stack, and trace now have a number of common modules; the number of common modules will be increased if debug and trace_stack are changed to use the new argument list printing program developed for trace. This argument list printing program is an extension of the program currently used by trace_stack; it was specifically written to be usable by all three debugging programs.

SUMMARY: Change debug and trace_stack to call print_arg_list, the new program mentioned above, and combine the three debuggers into a single bound segment. This work has already been done in a private version.

IMPLICATIONS: The output produced by trace_stack and by the .a request of debug will be slightly different. debug will be able to print the value of an argument of any PL/I scalar type. The documentation of debug will have to be updated.

MULTI-CHANGE REQUEST		MCR <u>722</u> Page <u>1</u> of <u>1</u>
TITLE: <u>New ring 1 gate macros.</u>		STATUS
AUTHOR: <u>P.A. Janson</u>		Written <u>8-16-74</u>
SOURCE: (if external) e.g., "User", "Marketing" <u>CSR</u>		Approved <u>8/20/74</u>
		Rejected
		Postponed
		Withdrawn
		Expires <u>2/20/75</u>

CLASSIFICATION	JUSTIFICATION	
<input type="checkbox"/> Incompatible Change	Marketing Requirement	Replaced by proposal MCR _____
<input type="checkbox"/> Extension	Conformance to Standard	Implemented in System _____
<input type="checkbox"/> Restriction	<input checked="" type="checkbox"/> Increased Consistency	Objections/Comments:
<input type="checkbox"/> Performance Improvement	Simplification	
<input checked="" type="checkbox"/> Reliability Improvement	Generalization	
<input checked="" type="checkbox"/> Security Impr	Bug Fix	

Use these headings: REASONS, SUMMARY, IMPLICATIONS, DETAILED PROPOSAL (Optional)

REASONS: Ring 1 gates, according to the current version of gate_macros.incl.mexp, set their linkage pointer (lp) by picking it up from the LOT of the ring they were invoked from. Firstly, this is a security violation: ring 1 gates should not trust the content of a LOT entry in an outer ring. Secondly, it is inconsistent with what hard-core gates do and any user ring gate should do.

SUMMARY: This MCR proposes to change a few lines of code in gate_macros.incl.mexp and to recompile ring 1 gates (deh_test_gate_, installation_tools_, message_segment_, tape_admin_) so as to have them pick their lp from the ring 1 LOT entry.

IMPLICATIONS: The change is fully compatible with what the current linker does. It also sets the LOT entry in ring 1 when snapping a link to a ring 1 gate. In addition the change will make ring 1 gates compatible with the design of the future user ring linker which will no longer maintain the LOT entry in the outer rings for the ring 1 gates.

MULTIPLY CHANGE REQUEST		MCP <u>723</u> Page <u>1</u> of <u>1</u>
TITLE: Fix bugs in basic		STATUS: <u> </u>
AUTHOR: <u>Barry L. Wolman</u>		Written: <u>740815</u>
SOURCE: (if external) e.g., "User", "Marketing"		Approved: <u>8/20/79</u>
		Rejected: <u> </u>
		Postponed: <u> </u>
		Withdrawn: <u> </u>
		Expires: <u>2/20/75</u>


CLASSIFICATION	JUSTIFICATION	Replaced by proposal MCP <u> </u>
<input type="checkbox"/> Incompatible Change	<input type="checkbox"/> Marketing Requirement	<input type="checkbox"/> Implemented in System <u> </u>
<input type="checkbox"/> Extension	<input type="checkbox"/> Conformance to Standard	Objections/Comments: <u> </u>
<input type="checkbox"/> Restriction	<input type="checkbox"/> Increased Consistency	
<input type="checkbox"/> Performance Improvement	<input type="checkbox"/> Simplification	
<input type="checkbox"/> Reliability Improvement	<input type="checkbox"/> Generalization	
<input type="checkbox"/>	<input checked="" type="checkbox"/> Bug Fix	
<input type="checkbox"/>	<input type="checkbox"/>	

Use these headings: REASONS, SUMMARY, IMPLICATIONS, DETAILED PROPOSAL (optional)

REASONS: The following bugs exist in the installed basic:

- No. 32: source program longer than 1000 lines causes fault in basic_lex
- No. 33: bad code is generated for $(1 + a(i))^2$
- No. 34: return without previous gosub sometimes causes fault
- No. 35: math functions not setting indicators properly; this causes problems with statements such as
if $\sin(x) = 0$ then ...
- No. 36: an array name appearing in more than one dim-statement is not diagnosed
- No. 37: use of operator with fractional values can cause process termination
- No. 38: instruction after instruction that causes underflow fault gets skipped due to change in behavior of FIM
- No. 39: underscore not allowed in subprogram name
- No. 40: illegal subprogram name in sub-statement causes fault if the sub-statement is the first statement in the program
- No. 41: char(*) arg not accepted in call of basic subprogram from PL/I program
- No. 42: subprogram name not properly supplied in error messages relating to incorrect call of subprogram
- No. 43: on num goto ... not properly split into tokens
- No. 44: store of control variable in for-next loop occurs after test is made instead of before as specified by manual.
- No. 45: for i = 0 to t step ... not properly split into tokens by EXL basic due to error in fix for bug 43
- No. 46: references to global variables are not correct if a function is called from another function that was called from another subprogram.

SUMMARY: Fix the bugs.



MULTI-COMPARISON REQUEST	MCR <u>724</u> Page <u>1</u> of <u>2</u>
TITLE: <u>Install new version of basic</u>	STATUS: <u> </u>
AUTHOR: <u>Barry L. Wolman</u>	Written: <u>740815</u>
SOURCE: (if external) e.g., "User", "Marketing"	Approved: <u>8/20/73</u>
	Rejected: <u> </u>
	Postponed: <u> </u>
	Withdrawn: <u> </u>
	Expires: <u>2/20/75</u>

CLASSIFICATION	JUSTIFICATION	REASON
<input type="checkbox"/> Incompatible Change	<input type="checkbox"/> Marketing Requirement	Replaced by proposal MCR _____
<input checked="" type="checkbox"/> Extension	<input type="checkbox"/> Conformance to Standard	Implemented in System _____
<input type="checkbox"/> Restriction	<input type="checkbox"/> Increased Consistency	Objections/Comments: _____
<input checked="" type="checkbox"/> Performance Improvement	<input type="checkbox"/> Simplification	
<input type="checkbox"/> Reliability Improvement	<input checked="" type="checkbox"/> Generalization	
<input type="checkbox"/>	<input checked="" type="checkbox"/> Bug Fix	
<input type="checkbox"/>	<input type="checkbox"/>	

Use these headings: REASONS, SUMMARY, IMPLICATIONS, DETAILED PROPOSAL (Optional)

REASONS:

1. The current version of basic uses fixed size tables for recording line numbers, data elements, and constants. These fixed size tables place a limit on the size of the program that can be compiled, and some relatively small programs can exceed a table size. Using very large sizes for these tables causes unnecessary page faults when compiling small programs.
2. In current version of basic, about 20% of compiler's time is spent in the procedure basic_, which does little more than loop calling the external procedures basic_lex and basic_statement. Making basic_lex and basic_statement be quick internal procedures of basic_ yields a 15% increase in speed of the compiler.

SUMMARY:

1. Change basic to use a storage strategy for its tables in which the tables are initially small and are located in the stack. When a table becomes full, it is copied into a pre-determined place in an external segment; if necessary, tables occurring after it in this segment are moved. Tables can continue to grow until the entire segment becomes full. This should allow programs of very large size to be compiled while enabling small programs to be compiled more efficiently.
2. Combine basic_, basic_lex, basic_statement, basic_object, basic_subprogram, and basic_error into a single program basic_. Storage formerly placed in an external segment for communication between these programs will be located in stack frame of basic_. The time required to compile the combined version is 50% greater

than the time required to compile basic_statement, which was the module that was usually re-compiled to fix bugs.

These changes have been checked out and are currently installed in the EXL version of basic_. The anticipated reduction in page faults and increase in speed have been verified. Compiling a real 1350 line program, the compiler speed went from 21,000 lines per minute to 24,000 lines per minute; a 10,000 line "toy" program was compiled in 20 seconds, which places an upper bound of 30,000 lines per minute on speed of compiler in present form.

IMPLICATIONS: The external interface of basic_ remains unchanged, so there should be no noticeable change to any program that calls basic_.

MULTIPLY CHANGE PROPOSAL		MCP 725 Page 1 of 1
TITLE: Error Checking by indent command	STATUS	
AUTHOR: T. Casey	Written	8-19-74
	Approved	8/27/74
	Rejected	
SOURCE: (if external) e.g., "User", "Marketing"	Postponed	
	Withdrawn	
	Expires	2/27/75

CLASSIFICATION	JUSTIFICATION	Replaced by proposal MCP _____
<input type="checkbox"/> Incompatible Change	<input type="checkbox"/> Marketing Requirement	Implemented in System _____
<input checked="" type="checkbox"/> Extension	<input type="checkbox"/> Performance to Standard	Objections/Comments:
<input type="checkbox"/> Restriction	<input type="checkbox"/> Increased Consistency	
<input type="checkbox"/> Performance Improvement	<input type="checkbox"/> Simplification	
<input checked="" type="checkbox"/> Reliability Improvement	<input checked="" type="checkbox"/> Generalization	
<input type="checkbox"/>	<input type="checkbox"/> Bug Fix	

Use these headings: REASONS, SUMMARY, IMPLICATIONS, DETAILED PROPOSAL (Optional)

REASONS: One of the errors that indent detects is unbalanced quotes ("Program ends in a string"). Unfortunately, from the point of the missing quote to the end of the program, the indentation is performed on the contents of what should have been quoted strings changing the white space in them in some way. These changes are often inconvenient to undo. The only way to protect against this currently is to always have the indented source put in a new segment, but this also involves some inconvenience, added to every use of indent (rename, delete, etc.) to obtain a single copy of the source after verifying that it is a good copy.

SUMMARY: Change indent so that, when the original segment is to be replaced, and errors have been detected, the input segment will not be replaced. Instead, a message will be printed on error_output, informing the user of this, and giving the path-name of the temporary segment containing the indented copy of the program.

IMPLICATIONS: This is an incompatible change from the present method of operation. However, since the most likely response of a user to errors during indentation is to fix the errors and indent again, this change should not cause any inconvenience.

MULTIPLE CHANGE REQUEST		MCP <u>726</u> Page <u>1</u> of <u>1</u>
TITLE: Implement status "names" option		STATUS: <u>1975</u>
AUTHOR: <u>Steve Herbst</u>		Written: <u>8-19-</u>
SOURCE: (if external) e.g., "User", "Marketing"		Approved: <u>8/27/74</u>
		Rejected:
		Postponed:
		Withdrawn:
		Expires: <u>2/27/75</u>

CLASSIFICATION	JUSTIFICATION	
<input type="checkbox"/> Incompatible Change	<input type="checkbox"/> Marketing Requirement	Replaced by proposal MCP _____
<input checked="" type="checkbox"/> Extension	<input type="checkbox"/> Conformance to Standard	Implemented in System _____
<input type="checkbox"/> Restriction	<input type="checkbox"/> Increased Consistency	Objections/Comments:
<input type="checkbox"/> Performance Improvement	<input type="checkbox"/> Simplification	
<input type="checkbox"/> Reliability Improvement	<input checked="" type="checkbox"/> Generalization	
<input type="checkbox"/>	<input type="checkbox"/> Bug Fix	
<input type="checkbox"/>	<input type="checkbox"/>	

Use these headings: REASONS, SUMMARY, IMPLICATIONS, DETAILED PROPOSAL (Optional)

REASONS: The status command should accept "-names" as well as "-name" to print an entry's multiple names.

SUMMARY: Recognize "-names" as a pseudonym for "-name".

MULTIPLE CHANGE REQUEST	MCP <u>727</u> Form <u>1 of 1</u>
TITLE: <u>Install pll_operators, any_to_any, and dec_ops_</u>	STATUS
AUTHOR: <u>R.A. Barnes</u>	Written <u>8-16-74</u> Approved <u>8/27/74</u> Rejected
SOURCE: (if external) e.g., "User", "Marketing"	Postponed Withdrawn Expires <u>2/27/75</u>

CLASSIFICATION	JUSTIFICATION	REASON
<input type="checkbox"/> Incompatible Change	<input type="checkbox"/> Marketing Requirement	Replaced by proposal MCP _____
<input type="checkbox"/> Extension	<input type="checkbox"/> Conformance to Standard	Implemented in System _____
<input type="checkbox"/> Restriction	<input type="checkbox"/> Increased Consistency	Objections/Comments:
<input type="checkbox"/> Performance Improvement	<input type="checkbox"/> Simplification	
<input type="checkbox"/> Reliability Improvement	<input type="checkbox"/> Generalization	
<input type="checkbox"/>	<input checked="" type="checkbox"/> Bug Fix	
<input type="checkbox"/>	<input type="checkbox"/>	

Use these headings: REASONS, SUMMARY, IMPLICATIONS, DETAILED PROPOSAL (Optional)

REASONS: To fix PL/I bugs: 1088, 1099, 1112, 1126, 1129, 1133, 1150, 1170, 1171, 1189, 1192, 1201, and 1202.

SUMMARY: Major fixes include proper signalling of conversion when converting from character string, return (bit(*)) which used to return all zeroes, and freeing of controlled storage.

IMPLICATIONS: None, except that this installation must precede next PL/I installation.

MULTI-STEP CHANGE PROJECT		MCP <u>728</u> Page <u>1</u> of <u>1</u>
TITLE: Add a wait for rewind completion to the detach entry for the nstd_tape dim		STATUS: <u>INIT</u>
AUTHOR: <u>Susan Barr</u>		Written: <u>8-5-74</u>
SOURCE: (if external) e.g., "User", "Marketing"		Approved: <u>8/27/74</u>
		Rejected: _____
		Postponed: _____
		Withdrawn: _____
		Expires: <u>2/27/75</u>

CLASSIFICATION	JUSTIFICATION	
Incompatible Change	Marketing Requirement	Replaced by proposal MCP _____
Extension	Conformance to Standard	Implemented in System _____
Restriction	<input checked="" type="checkbox"/> Increased Consistency	Objections/Comments: _____
Performance Improvement	Simplification	
Reliability Improvement	Generalization	
	Bug Fix	

Use these headings: REASONS, SUMMARY, IMPLICATIONS, DETAILED PROPOSAL (Optional)

REASONS: If the user of the nstd_dim issues a rewind order and then tries to detach the tape, the error code device busy is returned.

DETAILED PROPOSAL: Add code to the detach entry to check if the tape is rewinding, and if so, to go blocked until completion of the rewind, and then to send the unload order.

A similar check is already made for data transfer requests and order calls.

MULTIPLE CHANGE REQUEST		MCP <u>729</u> Page <u>1</u> of <u>1</u>
TITLE: <u>Fix bug in mseg_access_</u>		STATUS
AUTHOR: <u>Steve Herbst</u>		Written <u>8-20-74</u>
SOURCE: (if external) e.g., "User", "Marketing"		Approved <u>8/27/74</u>
		Rejected
		Postponed
		Withdrawn
		Expires <u>2/27/75</u>

CLASSIFICATION	JUSTIFICATION	REASON
<input type="checkbox"/> Incompatible Change	<input type="checkbox"/> Marketing Requirement	Replaced by proposal MCP _____
<input type="checkbox"/> Extension	<input type="checkbox"/> Conformance to Standard	Implemented in System _____
<input type="checkbox"/> Restriction	<input type="checkbox"/> Increased Consistency	Objections/Comments: Ensure that all arguments are copied and referenced only once.
<input checked="" type="checkbox"/> Performance Improvement	<input type="checkbox"/> Simplification	
<input type="checkbox"/> Reliability Improvement	<input type="checkbox"/> Generalization	
<input type="checkbox"/>	<input checked="" type="checkbox"/> Bug Fix	
<input type="checkbox"/>	<input type="checkbox"/> Unreported	

Use these headings: REASONS, SUMMARY, IMPLICATIONS, DETAILED PROPOSAL (Optional)

REASONS: mseg_access \$delete copies the input ACL to a condensed ACL structure with which to call hcs \$delete_acl_entries. Per-entry error codes are placed in this condensed ACL structure. They are never copied out to the caller's ACL structure.

SUMMARY: Copy back the per-entry error codes before returning.

MULTIPLE CHANGE PROPOSAL		MCP <u>730</u> Form <u> </u>
TITLE: Change mechanism of calling initial procedure in a new process.		STATUS: <u> </u>
AUTHOR: <u>Steve Webber</u>		Written <u>8-20-</u>
SOURCE: (if external) e.g., "User", "Marketing"		Approved <u>8/27/74</u>
		Rejected <u> </u>
		Postponed <u> </u>
		Withdrawn <u> </u>
		Expires <u>2/27/75</u>

CLASSIFICATION	JUSTIFICATION	Replaced by proposal MCP <u> </u>
<input type="checkbox"/> Incompatible Change	Marketing Requirement	Implemented in System <u> </u>
<input checked="" type="checkbox"/> Extension	Conformance to Standard	Objections/Comments: <u> </u>
<input type="checkbox"/> Restriction	<input checked="" type="checkbox"/> Increased Consistency	
<input checked="" type="checkbox"/> Performance Improvement	Simplification	
<input type="checkbox"/> Reliability Improvement	<input checked="" type="checkbox"/> Generalization	
<input type="checkbox"/> <u> </u>	<u> </u>	
<input type="checkbox"/> <u> </u>	Bug Fix	

Use these headings: REASONS, SUMMARY, IMPLICATIONS, DETAILED PROPOSAL (Optional)

REASONS: Some deficiencies exist in the current "init_admin" "process_overseer" mechanisms. In particular, the "direct" feature is not fully operational (the feature that allows a user to replace init_admin rather than process_overseer). Also, it is convenient for users to have a working directory established early in their process.

SUMMARY: see attached

IMPLICATIONS: Users will be able (if PDT, etc. say ok) to replace init_admin and therefore perform their own I/O attachments. Knowledge of how to do this is transient and users so doing it should be warned.

SUMMARY:

Today the answering service will accept a process overseer from a user logging in and pass it on to the newly created process (if allowed to by the PDT) in the pit. In addition, the answering service will pass on a request to have this program called directly rather than through "init_admin". (The mechanism for "direct" calling is not fully operational.)

The disadvantages with the current scheme are:

- 1) The "direct" feature is not fully operational,
- 2) The different kinds of processes (absentee, daemon, user, etc.) would probably best be served with separate "init_admin_" programs, and
- 3) Due to a coding oversight, the init_admin_ stack frame is not abandoned as it once was.

It is proposed that the above mechanism be replaced by the following:

- 1) init_proc (the initial program in a new process) which runs in ring 0 and sets up the KST via a call to initialize_kst and determines the init_admin_ to use should be changed to
 - a) get a pointer to the PIT
 - b) determine from the PIT the process type and call either daemon_init_admin_, absentee_init_admin_, or user_init_admin_ unless a direct process overseer has been specified in which case it is called.
- 2) The program init_admin_ should be (logically) split into the 3 programs mentioned above.
- 3) The program real_init_admin_ should be split into the appropriate parts.
- 4) The replacements to init_admin_ should release their stack frame before calling the process overseer or at least have a small stack frame.

The reason for having user_init_admin_ and process_overseer_ two distinct programs is so that users can generate their own process overseers without being told about the internal interfaces in user_init_admin_. Any direct process overseer, therefore, must have knowledge of internal interfaces which, by definition, are subject to change.